



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER  
Executive Director

### Division of Oil, Gas and Mining

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program September 20, 2010

Reviewed:

<b>Mine Name:</b> Wolf Creek Mine	<b>Permit Number:</b> S/013/0016
<b>Operator Name:</b> Leon & Sons Excavating LLC	<b>Inspection Date:</b> 09/25/2010
<b>Inspector(s):</b> L Heppler	<b>Time:</b> 3:00 PM
<b>Other Participants:</b> none	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**Bond Renewal Date:** 04-06-2010 **Bond Amount:** \$7,600 **Annual Permit fee** was paid when permitting action was initiated in 2010.

**Purpose of Inspection:** Routine annual inspection. This site was inspected as a small mine site on 01/07/2010

**Inspection Summary:** Operator has removed some of the rip rap material stockpiles, since the last inspection in January. No trash was noted on site. No erosion problems were noted on site. Two roads access the working face. Every effort should be made to salvage top soil from the site prior to mining.

Photos were taken to document site conditions.

**Conclusions and Recommendations:** It is the recommendation of the Division that the Operator to implement an interim seeding program of intermediate wheatgrass and smooth brome, so noxious weeds such as Canada and musk thistle will not dominate the site; it would also aid with dust suppression. OGM to continue annual inspections and monitor the site when in the area.

**Inspector's Signature**


LAH:eb

cc: Leon Casper

O:\M013-Duchesne\S0130016-WolfCreek\inspections\Insp-08252010.doc







Note stockpiles of riprap at the base of the regraded slope



Working face



Lower access road



Upper access roads